

SECRET

(When Filled In)

FILE INFO

30 NOV 71 85354

REPRODUCTION PROHIBITED

ACTION	1	DM	6	DIOP	11		16
	2		7	TRAIL	12		17
	3	LSA	8	"	13		18
	4	LB	9	TRAIL	14		19
	5		10	"	15		20

NNNS E C R E T 302245Z NOV 71 CITE

25X1

IDEALIST DM-1/3

25X1

REF A.

25X1

B.

C.

D.

DOE review completed.

SUBJ:

1. [] HAS RECEIVED AND EVALUATED THE T-35 MATERIAL FROM 25X1

[] THE FOLLOWING IS THE "BY FRAME" ACTIVITY:

25X1

FRAME	ACTIVITY
000 - 001	INITIAL DARKROOM LOADING
002 - 003	CYCLES FOLLOWING INSTALLATION IN THE CASE
004 - 005	CYCLES FOLLOWING INSTALLATION IN VEHICLE
006 - 016	TRACKER WENT TO A RUNAWAY CONDITION. SYSTEM VOLTAGE FOUND TO BE 32 VDC. VOLTAGE WAS ADJUSTED TO 29.5 VDC
017 - 019	CYCLE NORMAL AFTER VOLTAGE ADJUSTED
020 - 025	ARTICLE NOSE CONE WAS REMOVED AND TRACKER OPERATED ON ARTICLE POWER FOR AUDIBLE ABNORMALITIES.
026	GROUND TEST AT [] DEPLOYMENT SITE
027 - 028	SHOP POSTFLIGHT AFTER DOWNLOAD

25X1

25X1

2. [] EVALUATION INDICATED THAT THERE WERE NO INFLIGHT CYCLES ACCOMPLISHED WITH POSSIBLE CAUSE BEING THAT STATED IN REF A.

3. SINCE THE INTERVALOMETER BOARDS AND TRACKER ARE PRESENTLY AT [] WILL FORWARD SUBJECT MATERIAL.

25X1

SECRET